## CELOS

DovercourtW August 14, 2008

Playstructure	Description Of Components	Year	Deficiencies	Recommendations	Repair Costs	Labour Hours
Senior (Henderson)			This is a wood structure, 15 yrs. old	Replace	20,000.0	
Senior (Henderson)			the wood is uneven, splitting, rotting			
Senior (Henderson)			The platforms are uneven	Reset	300.0	40
Senior (Henderson)	Corkscrew climber(2)		Height of 60" doesn't comply	Adjust or remove	300.0	20
Senior (Henderson)	Chain climber		None			
Senior (Henderson)	3 ft. arch climber		None			
Senior (Henderson)	Ladder		None			
Senior (Henderson)	Steering wheel		None			
Senior (Henderson)	5 ft. arch climber		None			
Senior (Henderson)	Hand-over-hand climber		None			
Senior (Henderson)	4 ft. gang slide		None			
Senior (Henderson)	5 ft. slide		None			
	Swings: 3 bays w 4belt,2baby seats		None			
	Manuf.: Paris					
	Teeter- totter(Kompan)		None			
	Spring toy(Kompan)		None			
	Balance beams		None			
	BASE MATERIAL					
	Concrete sand		Compacted	Replace	25,000.0	300
					45,600.00	360.00