

Location	Ward	Year	Description Of Components	Deficiencies	Recommendations	Repair Costs	Labour Hours	Notes
Campbell Playground								
Campbell Playground	18		BASE MATERIAL					No Work is scheduled in the near future
Campbell Playground	18		Concrete sand	Compacted	Replace	25,000	280	
						25,000.00	280.00	
Carlton E.								
Carlton E.	18		BASE MATERIAL					No Work is scheduled in the near future
Carlton E.	18		Concrete sand	Compacted	Replace	8,000	100	
						8,000.00	100.00	
Carlton W.								
Carlton W.	18		BASE MATERIAL					No Work is scheduled in the near future
Carlton W.	18		Concrete sand	Compacted	Replace	18,000	200	
						18,000.00	200.00	
Dovercourt E.								
Dovercourt E.	18		BASE MATERIAL					
Dovercourt E.	18		Concrete sand	Compacted	Replace	4,000	80	\$75,000 is scheduled for 2009
						4,000.00	80.00	
Dovercourt W.								
Dovercourt W.	18		Senior Playstructure(Henderson)	This is a wood structure, 15 yrs.	Replace	20,000		\$75,000 is scheduled for 2009
Dovercourt W.	18		Senior Playstructure(Henderson)	Old the wood is uneven, splitting, rotting				
Dovercourt W.	18		Senior Playstructure(Henderson)	The platforms are uneven	Reset	300	40	
Dovercourt W.	18		Corkscrew climber(2)	Height of 60" doesn't comply	Adjust or remove	300	20	
Dovercourt W.	18		BASE MATERIAL					
Dovercourt W.	18		Concrete sand	Compacted	Replace	25,000	300	
						45,600.00	360.00	

Ward18-Summary

August 14, 2008
2 of 3

Location	Ward	Year	Description Of Components	Deficiencies	Recommendations	Repair Costs	Labour Hours	Notes
Dufferin Grove								
Dufferin Grove	18		Swings w 3 bays(4belt, 2baby seats)	Improper spacing, too narrow.	Remove one seat from each bay	2,000	30	\$75,000 is scheduled for 2009
Dufferin Grove	18		Senior playstructure	Non compliant	Replace	25,000	120	
Dufferin Grove	18		4"x4" rails around structure		Retrofit	2,000	20	
Dufferin Grove	18		Hand-over-hand climber	The post tops are flat	Cut at an angle or cover with caps	100	8	
Dufferin Grove	18		BASE MATERIAL					
Dufferin Grove	18		Mixed concrete sand & Hutcheson	Compacted	Remove and replace	20,000	200	
						49,100.00	378.00	
Dundas - St.Clarens								
Dundas - St.Clarens	18		BASE MATERIAL					
Dundas - St.Clarens	18		Hutcheson Playground sand	None				
						0.00	0.00	
Erwin Krickhan								
Erwin Krickhan	18		Swings: 2bays w 4belt seats(Paris)	Top beam is bent	Replace	500.0	32	No Work is scheduled in the near future
Erwin Krickhan	18		BASE MATERIAL		Top-up with 6" of similar sand	4,000.0	100	
Erwin Krickhan	18		Concrete sand	Compacted	Replace	20,000.0	200	
						24,500.00	332.00	
MacGregor								
MacGregor	18		BASE MATERIAL					No Work is scheduled in the near future
MacGregor	18		Concrete sand	Compacted	Replace	15,000.0	150	
						15,000.00	150.00	
McCormack								
McCormack	18		BASE MATERIAL					No Work is scheduled in the near future
McCormack	18		Concrete sand	Compacted	Replace	20,000.0	225	
						20,000.00	225.00	
Perth Square								
Perth Square	18		Swings: 3bays w 3belt,3baby seats Manuf.: Paris					No Work is scheduled in the near future
Perth Square	18		BASE MATERIAL					
Perth Square	18		Concrete sand	Compacted	Replace	25,000.0	250	
						25,000.00	250.00	

Ward18-Summary

August 14, 2008
3 of 3

Location	Ward	Year	Description Of Components	Deficiencies	Recommendations	Repair Costs	Labour Hours	Notes
Susan Tibaldi								
Susan Tibaldi	18		Senior Playstructure(Gametime)					No Work is scheduled in the near future
						0.00	0.00	
Wallace Emerson								
Wallace Emerson	18		Spiral slide(2)	Entrapment hazard, barriers req'd.	Fabricate barriers, fix entrapment	600	130	\$75,000 is scheduled for 2009
Wallace Emerson	18		BASE MATERIAL					
Wallace Emerson	18		Concrete sand	Compacted	Replace	12,000.0	150	
						12,600.00	280.00	
Westmoreland								
Westmoreland						0	0	No Work is scheduled in the near future
						0.00	0.00	
						246,800.00	2635.00	