

Playstructure	Description Of Components	Year	Deficiencies	Recommendations	Repair Costs	Labour Hours	Other Considerations
Junior	Slide						
Junior	Hand-over-hand climber						
Junior	3ft. double slide						
Junior	Steering wheel						
Junior	Teeter-totter(Kompan)						
Senior	Swings w 3 bays(4belt, 2baby seats)		Improper spacing, too narrow.	Remove one seat from each bay	2,000	30	
Senior	4"x4" rails around structure			Retrofit	2,000	20	
Senior	Hand-over-hand climber		The post tops are flat	Cut at an angle or cover with caps	100	8	
Senior	5ft. gang slide						
Senior	Ramp						
Senior	Bridge						
Senior	Chain ladder						
Senior	3ft. gang slide		Worn edges	Remove			
	4-way spring teeter-totter(Henderson)						
	1-spring toy(Kompan)						
	Junior playstructure(Kompan)						
	Senior playstructure		Non compliant	Replace	25,000	120	
	Swing set(3baby seats)		Non compliant to CSA Standard	Remove			
	4 Way Climber(arch climber)		20 years old plus, worn, splitting, rot				
	BASE MATERIAL						
	Mixed concrete sand & Hutcheson		Compacted	Remove and replace	20,000	200	
					<b>49,100.00</b>	<b>378.00</b>	