## COMMUNITY FEEDBACK

FOR THE DUFFERIN GROVE

### BUILDING RENOVATION









COMPILED BY JUTTA MASON, MAIL@CELOS.CA



Lights in the main room are always on maximum brightness, they can't be dimmed by rec staff

The current lighting situation is uncomfortable: there have been complaints of headaches and of people needing to leave the clubhouse because of the light

SOLUTION: DIMMERS WILL
MAKE THE CLUBHOUSE
MORE COMFORTABLE
AND ACCESSIBLE IN
DIFFERENT SITUATIONS



# 3 DOORS: MULTIPLE ISSUES



the main room feels more like a passage than a room



this door is too heavy for its opener mechanism



this door between the main room and lobby is installed backwards

- A There are 10 doors in the main room that may be why it feels a bit like a hallway rather than a place to stay.
- B The automatic door opener buttons break often and have to be repaired (on the main east- and west-facing doors). The doors seem to be too heavy for the opener mechanism.
- The glass doors to the kitchen and staff room have been covered up with paper blinds so no one can see inside.
- The northwest door to the main room is installed in reverse the push bar and emergency exit sign are on the wrong side.







tall kitchen shelving



tall main room shelving



the storeroom

# LOOKING BACK: THE OLD CLUBHOUSE



Gathering by the old wood stove

Community members and rec staff with hot chocolate by the fire pit

#### DIVIPLE SINGRADINE BURK

